



Ohio Revised Code

Section 4104.07 Inspector of boilers and unfired pressure vessels - application for examination - certification.

Effective: December 29, 2023

Legislation: Senate Bill 131

(A) Except as provided in division (E) of this section, an application for examination as an inspector of boilers and pressure vessels shall be in writing, accompanied by a fee of one hundred fifty dollars, upon a blank to be furnished by the superintendent of industrial compliance. Any moneys collected under this section shall be paid into the state treasury to the credit of the industrial compliance operating fund created in section 121.084 of the Revised Code.

(B) The superintendent shall determine if an applicant meets all the requirements for examination in accordance with rules adopted by the board of building standards under section 4104.02 of the Revised Code. An application shall be rejected which contains any willful falsification, or untruthful statements.

(C) An applicant shall be examined by the superintendent, by a written examination, prescribed by the board, dealing with the construction, installation, operation, maintenance, and repair of boilers and pressure vessels and their appurtenances, and the applicant shall be accepted or rejected on the merits of the applicant's application and examination.

(D) Upon a favorable report by the superintendent of the result of an examination, the superintendent shall immediately issue to the successful applicant a certificate of competency to that effect.

(E) The superintendent shall issue a certificate of competency in accordance with Chapter 4796. of the Revised Code to an applicant if either of the following applies:

(1) The applicant holds a license or certificate in another state.

(2) The applicant has satisfactory work experience, a government certification, or a private certification as described in that chapter as an inspector of boilers and pressure vessels in a state that does not issue that license or certificate.



AUTHENTICATED,
OHIO LEGISLATIVE SERVICE
COMMISSION
DOCUMENT #313974
