



Ohio Administrative Code

Rule 3745-68-81 Closure.

Effective: December 7, 2004

At closure, the owner or operator must remove all hazardous waste and hazardous waste residues (including, but not limited to, ash) from the thermal treatment process or equipment.

[Comment: At closure, as throughout the operating period, unless the owner or operator can demonstrate, in accordance with paragraph (C) or (D) of rule 3745-51-03 of the Administrative Code, that any waste removed from the thermal treatment process or equipment is not a hazardous waste, the owner or operator becomes a generator of hazardous waste and must manage such waste in accordance with all applicable requirements of Chapters 3745-52, 3745-53, 3745-65 to 3745-69, and 3745-256 of the Administrative Code.]
