



Ohio Administrative Code

Rule 1501:14-3-02 Minimizing acid drainage and acid water accumulation.

Effective: December 18, 2017

To minimize acid drainage and the accumulation of acid water, the operator shall, unless otherwise approved in the mining and reclamation plan, isolate any acid producing refuse material in a location that will minimize acid water formation and that will prevent such material from coming into contact with surface water, and promptly cover the acid producing refuse material with a minimum of three feet of non-acid producing material.
