



Ohio Administrative Code Rule 3745-205-65 Reporting - equipment leaks.

Effective: June 12, 2023

(A) A semiannual report shall be submitted by owners and operators subject to the requirements of rules 3745-205-50 to 3745-205-65 of the Administrative Code to the director by dates specified by the director. The report shall include the following information:

- (1) The U.S. EPA identification number, name, and address of the facility.
 - (2) For each month during the semiannual reporting period:
 - (a) The equipment identification number of each valve for which a leak was not repaired as required in paragraph (D) of rule 3745-205-57 of the Administrative Code.
 - (b) The equipment identification number of each pump for which a leak was not repaired as required in paragraphs (C) and (D)(6) of rule 3745-205-52 of the Administrative Code.
 - (c) The equipment identification number of each compressor for which a leak was not repaired as required in paragraph (G) of rule 3745-205-53 of the Administrative Code.
 - (3) Dates of hazardous waste management unit shutdowns that occurred within the semiannual reporting period.
 - (4) For each month during the semiannual reporting period, dates when the control device installed as required by rule 3745-205-52, 3745-205-53, 3745-205-54, or 3745-205-55 of the Administrative Code exceeded or operated outside of the design specifications as described in paragraph (E) of rule 3745-205-64 of the Administrative Code and as indicated by the control device monitoring required by rule 3745-205-60 of the Administrative Code and was not corrected within twenty-four hours, the duration and cause of each exceedance, and any corrective measures taken.
- (B) If, during the semiannual reporting period, leaks from valves, pumps, and compressors are



AUTHENTICATED,
OHIO LEGISLATIVE SERVICE
COMMISSION
DOCUMENT #305310

repaired as required in paragraph (D) of rule 3745-205-57, paragraphs (C) and (D)(6) of rule 3745-205-52, and paragraph (G) of rule 3745-205-53 of the Administrative Code, respectively, and the control device does not exceed or operate outside of the design specifications as described in paragraph (E) of rule 3745-205-64 of the Administrative Code for more than twenty-four hours, a report to the director is not required.