



## Ohio Administrative Code

### Rule 3701:1-58-103 Report of a leaking source.

Effective: [October 4, 2010](#)

---

A licensee shall file a report within five days if a leak test required by rule 3701:1-58-27 of the Administrative Code reveals the presence of one hundred eighty-five becquerels (0.005 microcurie) or more of removable contamination. The report must be filed with the address listed in rule 3701:1-40-04 of the Administrative Code. The written report must include the model number and serial number if assigned, of the leaking source; the radionuclide and its estimated activity; the results of the test; the date of the test; and the action taken.

---