



Ohio Administrative Code

Rule 3745-57-51 Closure.

Effective: January 7, 1983

At closure the owner or operator must remove all hazardous waste and hazardous waste residues (including, but not limited to, ash, scrubber waters, and scrubber sludges) from the incinerator site.

[Comment: At closure, as throughout the operating period, unless the owner or operator can demonstrate, in accordance with paragraph (D) of rule 3745-51-03 of the Administrative Code, that the residue removed from the incinerator is not a hazardous waste, the owner or operator becomes a generator of hazardous waste and must manage such waste in accordance with applicable requirements of the hazardous waste rules.]
